Cemetery Gravestone Conservation

Before and After Photos

Hadley , MA

Completed October 2022

Gravestone Services of New England
112 McAllister Road
Bedford, NH 03110
Telephone: (978) 821-9158
www.GravestoneServices.com

Please notice that all stones were treated with D/2 biological to remove lichen and will brighten over the coming months.

Digitized by the Internet Archive
in 2024 with funding from
Boston Public Library

https://archive.org/details/cemeterygravesto00grav_0

Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	1
Name	David Billings
Material	marble
Marker Type	Tablet on Base

Stone Condition Ambient dirt and biological growth, leaning, loose
Treatment Methods: Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack. Infilled cracks with Lithomex Lime mortar

Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	2
Name	Infant Billings
Material	marble
Marker Type	tablet
Stone Condition	Ambient dirt and biological growth, leaning
Treatment Methods:	Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack.



Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	01~01
Name	F. Smith
Material	slate
Marker Type	foot-stone
Stone Condition	Ambient dirt and biological growth, leaning
Treatment Methods:	Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack.

Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	02~17
Name	Unknown #1
Material	slate
Marker Type	foot-stone

Stone Condition Ambient dirt and biological growth, leaning

Treatment Methods: Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack.

Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	02~18
Name	Unknown #2
Material	slate
Marker Type	foot-stone
Stone Condition	Ambient dirt and biological growth, leaning
Treatment Methods:	Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack.

Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	02~19
Name	J.B.
Material	slate
Marker Type	foot-stone
Stone Condition	Ambient dirt and biological growth, leaning
Treatment Methods:	Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack.

Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	04~13
Name	Eliza Bartlet
Material	sandstone
Marker Type	tablet
Stone Condition	Ambient dirt and biological growth, delaminating
Treatment Methods:	Treatment with D/2 biological solution. Infill delaminating cracks with Lithomex Lime mortar

Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	04~31
Name	Father
Material	marble
Marker Type	Die on Base

Stone Condition Ambient dirt and biological growth, leaning, loose
Treatment Methods: Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack.Secured sections with Akemi Akepox.

Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	05~03
Name	Joanna Smith
Material	slate
Marker Type	tablet

Stone Condition Ambient dirt and biological growth, leaning

Treatment Methods: Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack.

Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	05~10
Name	Oliver Stockbridge
Material	slate
Marker Type	tablet

Stone Condition Ambient dirt and biological growth, leaning

Treatment Methods: Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack.

Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	05~11
Name	Infant Stockbridge
Material	slate
Marker Type	tablet

Stone Condition Ambient dirt and biological growth, leaning

Treatment Methods: Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack.

Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	05-15
Name	Capt. Lewis Jones
Material	slate
Marker Type	tablet
Stone Condition	Ambient dirt and biological growth, leaning
Treatment Methods:	Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack.

Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	05~16
Name	Frances Jones
Material	slate
Marker Type	tablet

Stone Condition Ambient dirt and biological growth, leaning

Treatment Methods: Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack.



Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	05~17
Name	Enoch M. Jones
Material	marble
Marker Type	tablet

Stone Condition Ambient dirt and biological growth, broken, fallen

Treatment Methods: Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack. Adhesive repair with Akemi Akepox and infill remaining cracks with Lithomex Lime Mortar.



Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	05~26
Name	Cotton Smith
Material	sandstone
Marker Type	obelisk

Stone Condition Ambient dirt and biological growth, delaminating

Treatment Methods: Treatment with D/2 biological solution. Infill delaminating cracks with Lithomex
Lime mortar

Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	05~32
Name	Samuel S. Hibbard
Material	marble
Marker Type	pedestal
Stone Condition	Ambient dirt and biological growth, leaning
Treatment Methods:	Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack.

Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	06~10
Name	Hannah Cadwell
Material	marble
Marker Type	tablet

Stone Condition Ambient dirt and biological growth, broken, fallen

Treatment Methods: Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack. Adhesive repair with Akemi Akepox and infill remaining cracks with Lithomex Lime Mortar.



Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	06~19
Name	Unknownl Smith
Material	marble
Marker Type	die in base

Stone Condition Ambient dirt and biological growth, fallen

Treatment Methods: Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack.Secured sections with Akemi Akepox.



Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	07~06
Name	**Deacon George Hibbard**
Material	marble
Marker Type	tablet
Stone Condition	Ambient dirt and biological growth, leaning
Treatment Methods:	Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack.

Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	07~46
Name	Mary Helen Howe
Material	marble
Marker Type	Die on Base

Stone Condition Ambient dirt and biological growth, leaning, loose
Treatment Methods: Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack.Secured sections with Akemi Akepox.

Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	08~04
Name	Hannah Lamson
Material	marble
Marker Type	tablet
Stone Condition	Ambient dirt and biological growth, leaning
Treatment Methods:	Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack.



Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	08~07
Name	Phua Hibbard
Material	marble
Marker Type	tablet
Stone Condition	Ambient dirt and biological growth, leaning
Treatment Methods:	Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack.



Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	08~09
Name	Elizabeth Smith
Material	marble
Marker Type	tablet
Stone Condition	Ambient dirt and biological growth, leaning
Treatment Methods:	Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack.

Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	08~15
Name	George D. Smith
Material	slate
Marker Type	tablet

Stone Condition Ambient dirt and biological growth, broken, fallen

Treatment Methods: Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack. Adhesive repair with Akemi Akepox and infill remaining cracks with Lithomex Lime Mortar.

Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	09~04
Name	Mother Scott
Material	marble
Marker Type	die on base

Stone Condition Ambient dirt and biological growth, broken, fallen

Treatment Methods: Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack. Adhesive repair with Akemi Akepox and infill remaining cracks with Lithomex Lime Mortar.

Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	09~05
Name	Israel Scott
Material	marble
Marker Type	tablet

Stone Condition Ambient dirt and biological growth, broken, fallen

Treatment Methods: Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack. Adhesive repair with Akemi Akepox and infill remaining cracks with Lithomex Lime Mortar.



Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	09~09
Name	Emily Scott Cleveland
Material	marble
Marker Type	Die on Base

Stone Condition Ambient dirt and biological growth, leaning, loose
Treatment Methods: Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack.Secured sections with Akemi Akepox.



Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	09~105
Name	Alfred Powers
Material	marble
Marker Type	tablet

Stone Condition Ambient dirt and biological growth, broken, fallen

Treatment Methods: Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack. Adhesive repair with Akemi Akepox and infill remaining cracks with Lithomex Lime Mortar.

Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	09~16
Name	Abigail B. Powers
Material	marble
Marker Type	tablet

Stone Condition Ambient dirt and biological growth, broken, fallen

Treatment Methods: Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack. Adhesive repair with Akemi Akepox and infill remaining cracks with Lithomex Lime Mortar.

Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	09~24
Name	Esther Belden
Material	marble
Marker Type	tablet in base
Stone Condition	Ambient dirt and biological growth, leaning
Treatment Methods:	Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack.

Note: Mortar from previous repair could not be removed without causing permanent damage



Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	09~27
Name	Unknown #3
Material	marble
Marker Type	tablet
Stone Condition	Ambient dirt and biological growth, leaning
Treatment Methods:	Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack.

Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	09~47
Name	Mary Louisa Howe
Material	marble
Marker Type	Die on Base

Stone Condition Ambient dirt and biological growth, leaning, loose
Treatment Methods: Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack.Secured sections with Akemi Akepox.

Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	10~02
Name	Harriet Skerry
Material	marble
Marker Type	tablet

Stone Condition Ambient dirt and biological growth, broken, fallen

Treatment Methods: Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack. Adhesive repair with Akemi Akepox and infill remaining cracks with Lithomex Lime Mortar.

Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	10~03
Name	Unknown #4
Material	marble
Marker Type	tablet

Stone Condition Ambient dirt and biological growth, leaning

Treatment Methods: Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack.

Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	10~04
Name	Alfred Hibbard
Material	marble
Marker Type	tablet on base
Stone Condition	Ambient dirt and biological growth, leaning
Treatment Methods:	Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack.

Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	10~05
Name	Unknown #5
Material	marble
Marker Type	tablet

Stone Condition Ambient dirt and biological growth, leaning

Treatment Methods: Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack.

Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	10~20
Name	Abigail B. Osborn
Material	marble
Marker Type	tablet
Stone Condition	Ambient dirt and biological growth, leaning
Treatment Methods:	Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack.

Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	**10~24**
Name	Orrin D. Frost
Material	marble
Marker Type	tablet on base
Stone Condition	Ambient dirt and biological growth, fallen
Treatment Methods:	Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack.

Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	10~29
Name	Jessie
Material	marble
Marker Type	Die on Base

Stone Condition Ambient dirt and biological growth, leaning, loose
Treatment Methods: Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack.Secured sections with Akemi Akepox.

Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	10~30
Name	Abbie L.
Material	marble
Marker Type	Die on Base

Stone Condition Ambient dirt and biological growth, leaning, loose
Treatment Methods: Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack.Secured sections with Akemi Akepox.

Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	10~35
Name	Mary C. Ware
Material	marble
Marker Type	Die on Base

Stone Condition Ambient dirt and biological growth, leaning, loose
Treatment Methods: Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack.Secured sections with Akemi Akepox.

Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	10~36
Name	Harriet Ware
Material	marble
Marker Type	Die on Base

Stone Condition Ambient dirt and biological growth, leaning, loose
Treatment Methods: Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack.Secured sections with Akemi Akepox.



Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	10~37
Name	Lauriston Ware
Material	marble
Marker Type	Die on Base

Stone Condition Ambient dirt and biological growth, leaning, loose
Treatment Methods: Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack.Secured sections with Akemi Akepox. Infilled cracks with Lithomex Lime mortar



Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	10~38
Name	Nellie M. Ware
Material	marble
Marker Type	Die on Base

Stone Condition Ambient dirt and biological growth, leaning, loose
Treatment Methods: Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack.Secured sections with Akemi Akepox. Infilled cracks with Lithomex Lime mortar

Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	11~31
Name	Orange W. Marsh
Material	marble
Marker Type	tablet

Stone Condition Ambient dirt and biological growth, leaning

Treatment Methods: Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack.

Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	√
Name	Ware
Material	marble
Marker Type	obelisk

Stone Condition Ambient dirt and biological growth, leaning, loose
Treatment Methods: Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack.Secured sections with Akemi Akepox.



Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	12~08
Name	Susie Russell
Material	marble
Marker Type	Die on Base

Stone Condition Ambient dirt and biological growth, leaning, loose
Treatment Methods: Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack.Secured sections with Akemi Akepox.

Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	12~09
Name	Nellie Russell
Material	marble
Marker Type	Die on Base

Stone Condition Ambient dirt and biological growth, leaning, loose
Treatment Methods: Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack.Secured sections with Akemi Akepox.

Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	12~16
Name	Electa Hilliard
Material	marble
Marker Type	tablet

Stone Condition Ambient dirt and biological growth, leaning

Treatment Methods: Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack.



Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	12~36
Name	Mother Comins
Material	marble
Marker Type	tablet on base
Stone Condition	Ambient dirt and biological growth, leaning
Treatment Methods:	Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack.

Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	12~37
Name	Father Comins
Material	marble
Marker Type	tablet on base
Stone Condition	Ambient dirt and biological growth, leaning
Treatment Methods:	Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack.



Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	12~43
Name	Father Tuttle
Material	marble
Marker Type	Die on Base

Stone Condition Ambient dirt and biological growth, leaning, loose
Treatment Methods: Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack.Secured sections with Akemi Akepox.

Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	12~44
Name	Mother Tuttle
Material	marble
Marker Type	Die on Base

Stone Condition Ambient dirt and biological growth, leaning, loose
Treatment Methods: Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack.Secured sections with Akemi Akepox.

Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	12~45
Name	Annie Tuttle
Material	marble
Marker Type	Die on Base

Stone Condition Ambient dirt and biological growth, leaning, loose
Treatment Methods: Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack.Secured sections with Akemi Akepox.

Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	13~03
Name	Melinda Pierce
Material	marble
Marker Type	tablet on Base

Stone Condition Ambient dirt and biological growth, leaning, loose
Treatment Methods: Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack.Secured sections with Akemi Akepox.

Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	13~04
Name	Lucius Pierce
Material	marble
Marker Type	tablet on Base

Stone Condition Ambient dirt and biological growth, leaning, loose
Treatment Methods: Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack.Secured sections with Akemi Akepox.



Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	13~26
Name	Frederick S. Russell
Material	marble
Marker Type	tablet
Stone Condition	Ambient dirt and biological growth, leaning
Treatment Methods:	Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack.

Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	13~34
Name	Tuttle
Material	marble
Marker Type	pedestal
Stone Condition	Ambient dirt and biological growth, leaning
Treatment Methods:	Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack.



Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	14~02
Name	Susan W.Perkins
Material	marble
Marker Type	Die on Base

Stone Condition Ambient dirt and biological growth, leaning, loose
Treatment Methods: Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack.Secured sections with Akemi Akepox.

Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	14~14
Name	Emily Marshh
Material	marble
Marker Type	tablet on Base

Stone Condition Ambient dirt and biological growth, leaning

Treatment Methods: Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack.
Note: Mortar from previous repair could not be removed without causing permanent damage

Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	15~03
Name	M. L.
Material	granite
Marker Type	Die on Base

Stone Condition Ambient dirt and biological growth, leaning, loose
Treatment Methods: Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack.Secured sections with Akemi Akepox.

Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	15~05
Name	Emory H. Davis
Material	granite
Marker Type	Die on Base

Stone Condition Ambient dirt and biological growth, leaning, loose
Treatment Methods: Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack.Secured sections with Akemi Akepox.

Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	15~14
Name	Horatio Hurd
Material	marble
Marker Type	tablet on Base

Stone Condition Ambient dirt and biological growth, leaning, loose
Treatment Methods: Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack.Secured sections with Akemi Akepox.

Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	15~20
Name	Geo. A. Boice
Material	marble
Marker Type	tablet

Stone Condition Ambient dirt and biological growth, leaning, loose
Treatment Methods: Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack.Secured sections with Akemi Akepox.

Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	15~22
Name	John Miller
Material	marble
Marker Type	Die on Base

Stone Condition Ambient dirt and biological growth, leaning, loose
Treatment Methods: Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack.Secured sections with Akemi Akepox.

Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	15~23
Name	Mary E. Miller
Material	marble
Marker Type	Die on Base

Stone Condition Ambient dirt and biological growth, leaning, loose
Treatment Methods: Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack.Secured sections with Akemi Akepox.

Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	16~12
Name	Infant Russell
Material	marble
Marker Type	tablet in Base

Stone Condition Ambient dirt and biological growth, leaning, loose
Treatment Methods: Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack.Secured sections with Lithomex Lime Mortar.

Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	16~19
Name	Chauncey Trusk
Material	granite
Marker Type	Die on Base

Stone Condition Ambient dirt and biological growth, leaning, loose
Treatment Methods: Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack.Secured sections with Akemi Akepox.

Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	16~20
Name	Lucinda Lawrence
Material	marble
Marker Type	Die on Base

Stone Condition Ambient dirt and biological growth, leaning, loose
Treatment Methods: Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack.Secured sections with Akemi Akepox.

Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	17~04
Name	F.H. L.
Material	granite
Marker Type	foot-stone

Stone Condition Ambient dirt and biological growth, leaning

Treatment Methods: Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack.

Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	17~17
Name	Fred
Material	marble
Marker Type	Die on Base

Stone Condition Ambient dirt and biological growth, leaning, loose
Treatment Methods: Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack.Secured sections with Akemi Akepox.

Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	17~18
Name	Nellie
Material	marble
Marker Type	Die on Base

Stone Condition Ambient dirt and biological growth, leaning, loose
Treatment Methods: Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack.Secured sections with Lithomex Lime Mortar.

Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	17~19
Name	Chester D. Ingraham
Material	marble
Marker Type	tablet on Base

Stone Condition Ambient dirt and biological growth, leaning, loose
Treatment Methods: Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack.Secured sections with Akemi Akepox.

Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	18~09
Name	William L. Williams
Material	slate
Marker Type	tablet

Stone Condition Ambient dirt and biological growth, broken, fallen

Treatment Methods: Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack. Adhesive repair with Akemi Akepox and infill remaining cracks with Lithomex Lime Mortar.

Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	18~12
Name	Chester Cook
Material	marble
Marker Type	tablet on Base

Stone Condition Ambient dirt and biological growth, leaning, loose
Treatment Methods: Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack.Secured sections with Akemi Akepox.

Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	18~13
Name	Laura Barber
Material	marble
Marker Type	Die on Base

Stone Condition Ambient dirt and biological growth, leaning, loose
Treatment Methods: Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack.Secured sections with Akemi Akepox.

Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	18~14
Name	Lucy A. Cook
Material	marble
Marker Type	tablet on Base

Stone Condition Ambient dirt and biological growth, leaning, loose
Treatment Methods: Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack.Secured sections with Lithomex Lime Mortar.

Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	18~15
Name	Fred Cook
Material	marble
Marker Type	Die on Base

Stone Condition Ambient dirt and biological growth, leaning, loose
Treatment Methods: Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack.Secured sections with Akemi Akepox.



Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	18~19
Name	Willie Dickinson
Material	marble
Marker Type	tablet on Base

Stone Condition Ambient dirt and biological growth, leaning, loose
Treatment Methods: Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack.Secured sections with Akemi Akepox.

Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	18~21
Name	Caleb D. Dickinson
Material	marble
Marker Type	tablet on Base

Stone Condition Ambient dirt and biological growth, leaning, loose
Treatment Methods: Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack.Secured sections with Akemi Akepox.

Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	18~22
Name	Tryphena R Dickinson
Material	marble
Marker Type	tablet

Stone Condition Ambient dirt and biological growth, leaning, loose
Treatment Methods: Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack.Secured sections with Akemi Akepox and infill remaining cracks with Lithomex Lime Mortar.

Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	19~02
Name	Unknown # 5
Material	marble
Marker Type	tablet

Stone Condition Ambient dirt and biological growth, leaning

Treatment Methods: Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack.

Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	19~05
Name	Enos Henry Williams
Material	marble
Marker Type	Die on Base

Stone Condition Ambient dirt and biological growth, leaning, loose
Treatment Methods: Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack.Secured sections with Akemi Akepox.

Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	19~13
Name	Leonidas D. Miller
Material	marble
Marker Type	tablet on Base

Stone Condition Ambient dirt and biological growth, leaning, loose
Treatment Methods: Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack.Secured sections with Akemi Akepox.

Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	19~18
Name	Mary Hunt
Material	marble
Marker Type	tablet on Base

Stone Condition	Ambient dirt and biological growth, leaning
Treatment Methods:	Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack.

Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	20~13
Name	Elizabeth Hemenway
Material	marble
Marker Type	tablet

Stone Condition Ambient dirt and biological growth, broken, fallen

Treatment Methods: Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack. Adhesive repair with Akemi Akepox and infill remaining cracks with Lithomex Lime Mortar.

Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	20~14
Name	Eliphalet Hemenway
Material	marble
Marker Type	tablet

Stone Condition Ambient dirt and biological growth, broken, fallen

Treatment Methods: Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack. Adhesive repair with Akemi Akepox and infill remaining cracks with Lithomex Lime Mortar.

Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	20~14A
Name	G.M. R.
Material	marble
Marker Type	foot-stone

Stone Condition Ambient dirt and biological growth, leaning

Treatment Methods: Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack.

Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	20~15
Name	Sylvia Hemenway
Material	marble
Marker Type	tablet on Base

Stone Condition Ambient dirt and biological growth, leaning, loose
Treatment Methods: Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack.Secured sections with Lithomex Lime Mortar.

Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	22~08
Name	Henry C. (Father) Comins
Material	marble
Marker Type	Die on Base

Stone Condition Ambient dirt and biological growth, leaning, loose
Treatment Methods: Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack.Secured sections with Akemi Akepox and infill remaining cracks with Lithomex Lime Mortar.

Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	22~09
Name	Marcy Wright
Material	marble
Marker Type	Die on Base

Stone Condition Ambient dirt and biological growth, leaning, loose
Treatment Methods: Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack.Secured sections with Akemi Akepox.

Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	22~18
Name	Scott
Material	granite
Marker Type	Die on Base

Stone Condition Ambient dirt and biological growth, leaning, loose
Treatment Methods: Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack.Secured sections with Akemi Akepox.

Gravestone Services of New England, LLC

Cemetery	North Hadley Cemetery
Lot #	22~21
Name	Mable Ware
Material	marble
Marker Type	Die on Base

Stone Condition Ambient dirt and biological growth, leaning, loose
Treatment Methods: Treatment with D/2 biological solution. Reset to level and plumb with 3/4 inch hard-pack.Secured sections with Akemi Akepox.

20 Additional Gravestone repairs

North Hadley Cemetery

MOTHER



CLARY ALD
wife of
JOHN BELLS
who
Feb. 28, 1850,
Aged 33.

MARY





Old Hadley Cemetery

ABIGAIL SMITH
AGE. 7. 1825.
SEPT. 24. 1812.

Hockanum Cemetery


DONALD SCOBORIA MILES
JULY 31 1920 — JUNE 18 2000
NANCY RUTTER MILES
JAN. 30. 2018